


FT-480 smeter mod**Author:** sylvain L

A simple modification just for fun... Add a S-Meter on a ft-480r.

Open the top cover and find the purple wire in the white connector with 12 wires in the left side...Just cut the purple wire and connect it to a s-Meter positive with purple and negative with ground and add a potentiometer to adjust the meter level thats all...it's works well and i can give a good signal report.



This article is printed with permission from mods.dk the 01 Aug 2010. This printed article must only be used for non-commercial purposes; this is only for private use.

© Copyright mods.dk 1996 - 2010